

Haltec Digital Inflator

On Branick N2 Equipment


Quick Tips



Always make sure hose chucks are securely attached to the valve stem (no leakage).



To insure tire pressure accuracy, allow 20 seconds for tire pressure to equalize before disconnecting hoses from tires. *And then...*



***Quickly* turn the red valve handle to the stop position.**